

WESTERN PACIFIC RAILROAD MUSEUM

ROADMASTER BULLETIN #4


November 23, 2015

- 1. Roadmaster Bulletin #3 is cancelled.**

- 2. Effective upon issue of this bulletin, speed limit on the balloon track from the Malfunction Jct. station sign to the Milward Switch station sign, inclusive, is 5 mph for all trains and engines until further notice. No flags are displayed, since the limits are named points, identified by signs.**

- 3. All crews will be continuously observant of track conditions on the balloon during all movements, and will report any suspected or observed defects to the proper authority promptly.**

GT Elems
Roadmaster, WPRM
Member, FRRS Board of Directors



SJ Habeck
Yardmaster, WPRM
Vice-President, FRRS