

SN 1642 Restoration Update



Upper Left - Work continues on the 1642 with more DAP applied Monday 6/1/20 afternoon in preparation of more brown primer.

Middle left - Work continues on the 1642 with more DAP applied Monday 6/1/20 afternoon in preparation of more brown primer. Duane Vander Veen has been working on replacing the wood on the B end of the SN caboose. Here we see the replacement wood on floor and beside the center sill. 8/18/20

Lower Left - The work on the side with the final applications of DAP is nearing completion. 8/18/20

Above - Duane Vander Veen has been making steady progress on the SN 1642 platform on the B end. 9/30/20

- Photos by
Greg Elems





Left - A view of Duane's work on the SN 1642 end platform and door jam. 9/30/20

Above - After Duane sanded the metal bracing and frame, he applied primer. Duane has put a lot of time on this caboose and his skill and care show. 10/22/20

Below - Duane continuing his work on the SN 1642, seen here sanding on the metal frame. 10/22/20

- Photos by Greg Elems

